

Inspection Photos  
Location Name: USA Amoco A-A 1  
API: 05-081-06414



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. Location not visible from battery sign.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 689801000

Inspection Photos  
Location Name: USA Amoco A-A 1  
API: 05-081-06414



**Photo 3. Previous operator on tank labels. Vegetation on and in berm.**



**Photo 4. Previous operator on tank labels. Vegetation on and in berm.**