

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2018

Submitted Date:

04/02/2018

Document Number:

685304565**FIELD INSPECTION FORM**

Loc ID 326067	Inspector Name: St John, William (Cal)	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 4 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested															
<b>Operator Information:</b> OGCC Operator Number: <u>10000</u> Name of Operator: <u>BP AMERICA PRODUCTION COMPANY</u> Address: <u>380 AIRPORT RD</u> City: <u>DURANGO</u> State: <u>CO</u> Zip: <u>81303</u>																			
<b>Contact Information:</b> <table border="1"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Beebe, Sabre</td> <td>970-779-9398</td> <td>Sabre.Beebe@bp.com</td> <td><a href="#">SW Inspection Reports</a></td> </tr> <tr> <td>Inspections, All</td> <td></td> <td>SanJuanCOGCC@bp.com</td> <td><a href="#">SW Inspection Reports</a></td> </tr> </tbody> </table>					Contact Name	Phone	Email	Comment	Beebe, Sabre	970-779-9398	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>	Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>			
Contact Name	Phone	Email	Comment																
Beebe, Sabre	970-779-9398	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>																
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>																
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>215812</td> <td>WELL</td> <td>PR</td> <td>03/16/1990</td> <td>GW</td> <td>067-07417</td> <td>MW JOHNSON A 1</td> <td>PR</td> </tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	215812	WELL	PR	03/16/1990	GW	067-07417	MW JOHNSON A 1	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status												
215812	WELL	PR	03/16/1990	GW	067-07417	MW JOHNSON A 1	PR												

**General Comment:**

Inspection conducted in response to noise complaints 200445644 and 200445646.

A-scale sound survey conducted for noise from pumping unit was accomplished 3/26/2018 document number 685200425. Corrective actions resulting from this inspection contained in equipment and stormwater sections are still applicable.

C-scale survey attempt at residence to investigate complainant's description of "thudding" noise experienced inside homes were not accomplished due to wind speeds in excess of 5 mph. Wind speeds were 10 - 12 mph with gust over 20 mph.

**Inspected Facilities**Facility ID: 215812 Type: WELL API Number: 067-07417 Status: PR Insp. Status: PR**Complaint**Comment: [See document numbers 200445644 and 200445646. Additional attempt will be made to complete C-scale sound survey.](#)

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401595594	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423362">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4423362</a>