

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2018

Submitted Date:

03/29/2018

Document Number:

680001635**FIELD INSPECTION FORM**
 Loc ID 426976 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 200149Name of Operator: ATLAS RESOURCES LLC DBA ATLAS ROCKIES LLCAddress: 3500 MASSILLON ROAD #100City: UNIONTOWN State: OH Zip: 44685**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name   | Phone         | Email                     | Comment                         |
|----------------|---------------|---------------------------|---------------------------------|
| Walker, Chris  | (817)439-4561 | cwalker@atlasenergy.com   | <a href="#">All Inspections</a> |
| Ferrin, Jeremy |               | jeremy.ferrin@state.co.us |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 426960      | WELL | PR     | 10/24/2012  | GW         | 095-06387 | MURRAY 943-34-31 | SI          |

**General Comment:**[Routine inspection](#)

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Trail through farm ground |       |  |
| Corrective Action  |                           | Date: |  |

Overall Good: ☐

|                      |                                  |       |  |
|----------------------|----------------------------------|-------|--|
| <b>Signs/Marker:</b> |                                  |       |  |
| Type                 | WELLHEAD                         |       |  |
| Comment:             | Lease sign by well               |       |  |
| Corrective Action:   |                                  | Date: |  |
| Type                 | BATTERY                          |       |  |
| Comment:             | Lease sign mounted on meter shed |       |  |
| Corrective Action:   |                                  | Date: |  |

Emergency Contact Number:

Comment: Non-working emergency contact number.

Corrective Action: Install sign to comply with Rule 210.d.

Date: 04/29/2018

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                           |                                               |       |                 |
|---------------------------|-----------------------------------------------|-------|-----------------|
| <b>Equipment:</b>         |                                               |       | corrective date |
| Type: Ancillary equipment | # 1                                           |       |                 |
| Comment:                  | Gas scrubber                                  |       |                 |
| Corrective Action:        |                                               | Date: |                 |
| Type: Gas Meter Run       | # 1                                           |       |                 |
| Comment:                  |                                               |       |                 |
| Corrective Action:        |                                               | Date: |                 |
| Type: Pump Jack           | # 1                                           |       |                 |
| Comment:                  | 114 Weatherford, prime mover has been removed |       |                 |
| Corrective Action:        |                                               | Date: |                 |
| Type: Vertical Separator  | # 1                                           |       |                 |
| Comment:                  | In meter shed                                 |       |                 |
| Corrective Action:        |                                               | Date: |                 |

**Venting:**

|          |    |  |  |
|----------|----|--|--|
| Yes/No   | NO |  |  |
| Comment: |    |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

### Location Construction

Location ID: 426960 CDP: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:**

Corrective Action:  Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:  Date: \_\_\_\_\_

**Comment:**

**Corrective Action:**  Date: \_\_\_\_\_

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**Facility ID: 426960 Type: WELL API Number: 095-06387 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut in, No production reports have been submitted since June 2017.Corrective Action: Submit sundry notice for status of well and submit production reports.Date: 04/29/2018

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: DRY LAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: DRY LAND \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other            | Pass            | Other                   | Pass                  |               |                          |         |

Comment: [Access and unused areas of the location are farmed over.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description            | URL                                                                                                                                                                 |
|--------------|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 401592166    | INSPECTION SUBMITTED   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419226">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419226</a> |
| 680001662    | Inspection Photographs | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419207">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4419207</a> |