

Inspection Photos

Loc# 335669

Operator: Caerus

Inspection Number: 680102840

Inspection Date: 3/29/2018





Photo#1:
Overview of Location to North.

March 29 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 335669



Photo#2:
Storage area is situated at SW corner of Location.

March 29 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources


Inspection Photos: Caerus Loc# 335669



Photo#3: Close up views of equipment / supplies stored in area at Southwest corner of Location.

Photo#4:

March 29 2018



Photo#5:

Close up views of equipment / supplies stored in area at Southwest corner of Location.

Photo#6:

March 29 2018



Photo#7:
East side of Access road ditch needs maintenance.

Photo#8:

March 29 2018



Photo#9:
Concrete Debris at edge of Pad .

March 29 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Loc# 335669