

# *Inspection Photos*

*Loc# 335941*

*Operator: Caerus*

*Inspection Number: 680102850*

*Inspection Date: 3/29/2018*





**Photo#1:**

Overview of Location to North. Arrow indicates Fuel tank referenced in Unused equipment section.

March 29 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335941



Photo#2:  
Interim Reclamation area on West side of Location.

March 29 2018



Photo#3:

Fuel tank stored on West edge of Pad. Arrow indicates unused Pipe stored on Location

March 29 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335941



Photo#4:  
Overview of Pit; South to North.

March 29 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335941