

# Final Reclamation Inspection

April 5, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-069-06204

Inspection Document #: 682403457

Larimer County, CO

NWSE Section 36 T4N R69W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: STATE #2-36  
Well API: 05-069-06204



**Photo 1.** Riser #1 taken north of the well location on May 31, 2017. Lat/Long coordinates= 40.26902, -105.06190.



**Photo 2.** Riser #1 taken north of the well location on April 5, 2018. Riser now has flagging material but has not been removed.

Inspection Photos  
Location Name: STATE #2-36  
Well API: 05-069-06204



**Photo 3.** Riser #2 taken northeast of the well location on May 31, 2017. Lat/Long coordinates= 40.26906, -105.05868.



**Photo 4.** Riser #2 taken northeast of the well location on April 5, 2018. See comments under Photo 2.

Inspection Photos  
Location Name: STATE #2-36  
Well API: 05-069-06204



**Photo 5.** Riser #3 taken northeast of the well location on May 31, 2017. Lat/Long coordinates= 40.26908, -105.05589.



**Photo 6.** Riser #3 taken northeast of the well location on April 5, 2018. See comments under Photo 2.

Inspection Photos  
Location Name: STATE #2-36  
Well API: 05-069-06204



**Photo 7.** Riser #4 taken northeast of the well location on May 31, 2017. Lat/Long coordinates= 40.26917, -105.05555.



**Photo 8.** Riser #4 taken northeast of the well location on April 5, 2018. See comments under Photo 2. See comments under Photo 2.