

Location Name: Churchill Remediation 10302 Inspection Date: 4/9/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Churchill Remediation 10302 Inspection Date: 4/9/2018



From well pad looking east.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Churchill Remediation 10302 Inspection Date: 4/9/2018



Reclaimed pit area on east side of well pad.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Churchill Remediation 10302 Inspection Date: 4/9/2018



Looking west toward well pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Churchill Remediation 10302 Inspection Date: 4/9/2018



04.09.2018 08:40

Looking west toward well pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources