

Location Name: Churchill Remediation 10302 Inspection Date: 4/9/2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Churchill Remediation 10302 Inspection Date: 4/9/2018



Southern edge of well pad and fenced off pad reclamation area.



Location Name: Churchill Remediation 10302 Inspection Date: 4/9/2018



Reclaimed area on south side of well pad.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Churchill Remediation 10302 Inspection Date: 4/9/2018



Reclaimed area on south side of well pad.



Location Name: Churchill Remediation 10302 Inspection Date: 4/9/2018



Looking north toward well pad.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources