

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Mar 13, 2018 6:54:32 AM MDT
Server Receive Date:	Mar 13, 2018 6:58:34 AM MDT
Reference Number:	20180313-1874642473
Location:	3601 N 1st St, Bloomfield, NM 87413, United States
	Mar 13, 2018 6:54:24 AM MDT [View Map]

Information

Name	celkins@gobrainstorm.net
Date	Mar 12, 2018
Well Name	MAESTAS GAS UNIT A 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Fencing Erosion Repairs Install Rock Run Down Clean Up Contaminated Soils Replaced/Repaired Tank Signs Grading of Well Pad

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos

