

Inspection Photos  
Well Name: Federal 2-6H  
Location ID: 424424



**Photo 1. Erosion at gates with sediment migration into vegetation.**



**Photo 2. Erosion at gates with sediment migration into vegetation.**