

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2018

Submitted Date:

04/07/2018

Document Number:

680102842**FIELD INSPECTION FORM**

Loc ID 335690	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 2 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoil ndgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429281	WELL	XX	05/06/2014	LO	045-21516	N Parachute UWF15A-05K04596	RI
429282	WELL	XX	05/05/2014	LO	045-21517	N Parachute UWF13C-04K04596	RI
429283	WELL	XX	05/05/2014	LO	045-21518	N Parachute UWF07D-05K04596	RI
429284	WELL	XX	06/13/2014	LO	045-21519	N Parachute UWF09B-05K04596	RI
429286	WELL	XX	05/05/2014	LO	045-21521	N Parachute UWF10D-05K04596	RI
429287	WELL	XX	05/05/2014	LO	045-21522	N Parachute UWF12A-04K04596	RI
429288	WELL	XX	05/06/2014	LO	045-21523	N Parachute UWF15B-05K04596	RI
429289	WELL	XX	05/05/2014	LO	045-21524	N Parachute UWF10E-05K04596	RI
429290	WELL	XX	05/05/2014	LO	045-21525	N Parachute UWF12E-04K04596	RI
429292	WELL	XX	05/05/2014	LO	045-21527	N Parachute UWF13A-04K04596	RI
429294	WELL	XX	04/30/2014	LO	045-21529	N Parachute UWF07C-05K04596	RI
429296	WELL	XX	05/05/2014	LO	045-21531	N Parachute UWF13E-04K04596	RI
429297	WELL	XX	05/05/2014	LO	045-21532	N Parachute UWF13B-04K04596	RI
429298	WELL	XX	05/06/2014	LO	045-21533	N Parachute UWF15C-05K04596	RI
429299	WELL	XX	05/05/2014	LO	045-21534	N Parachute UWF10C-05K04596	RI
429300	WELL	XX	05/05/2014	LO	045-21535	N Parachute UWF07E-05K04596	RI

429301	WELL	XX	05/05/2014	LO	045-21536	N Parachute UWF10A-05K04596	RI
429302	WELL	XX	04/30/2014	LO	045-21537	N Parachute UWF05E-04K04596	RI
429306	WELL	XX	05/15/2014	LO	045-21541	N Parachute UWF05D-04K04596	RI
429307	WELL	XX	05/05/2014	LO	045-21542	N Parachute UWF12C-04K04596	RI
429308	WELL	XX	04/30/2014	LO	045-21543	N Parachute UWF05C-04K04596	RI
429309	WELL	XX	05/05/2014	LO	045-21544	N Parachute UWF13D-04K04596	RI

General Comment:

[This is a Reclamation Inspection for Twenty-two XX Wells with Permits Expired in 2016 on this Location.](#)

Inspected Facilities				
Facility ID: <u>429281</u>	Type: <u>WELL</u>	API Number: <u>045-21516</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429282</u>	Type: <u>WELL</u>	API Number: <u>045-21517</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429283</u>	Type: <u>WELL</u>	API Number: <u>045-21518</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429284</u>	Type: <u>WELL</u>	API Number: <u>045-21519</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429286</u>	Type: <u>WELL</u>	API Number: <u>045-21521</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429287</u>	Type: <u>WELL</u>	API Number: <u>045-21522</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429288</u>	Type: <u>WELL</u>	API Number: <u>045-21523</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429289</u>	Type: <u>WELL</u>	API Number: <u>045-21524</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429290</u>	Type: <u>WELL</u>	API Number: <u>045-21525</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429292</u>	Type: <u>WELL</u>	API Number: <u>045-21527</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429294</u>	Type: <u>WELL</u>	API Number: <u>045-21529</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429296</u>	Type: <u>WELL</u>	API Number: <u>045-21531</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429297</u>	Type: <u>WELL</u>	API Number: <u>045-21532</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429298</u>	Type: <u>WELL</u>	API Number: <u>045-21533</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429299</u>	Type: <u>WELL</u>	API Number: <u>045-21534</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429300</u>	Type: <u>WELL</u>	API Number: <u>045-21535</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429301</u>	Type: <u>WELL</u>	API Number: <u>045-21536</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429302</u>	Type: <u>WELL</u>	API Number: <u>045-21537</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>429306</u>	Type: <u>WELL</u>	API Number: <u>045-21541</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>

Inspector Name: Colby, Lou

Facility ID:	429307	Type:	WELL	API Number:	045-21542	Status:	XX	Insp. Status:	RI
Facility ID:	429308	Type:	WELL	API Number:	045-21543	Status:	XX	Insp. Status:	RI
Facility ID:	429309	Type:	WELL	API Number:	045-21544	Status:	XX	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: There are Twenty-two XX Wells with Permits Expired in 2016 on this Location.

Corrective Action: Abandon APDs for Wells with expired Permits by 5/7/18. Date **05/07/2018**

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401600201	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428181
680102843	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4428177