

S.PARACHUTE TBI 36-23

Api: 05-045-07734

Inspection # 689701269



Location photo.

S.PARACHUTE TBI 36-23

Api: 05-045-07734

Inspection # 689701269



2" tubing on edge of location.

S.PARACHUTE TBI 36-23

Api: 05-045-07734

Inspection # 689701269



Unused chemical lines.

S.PARACHUTE TBI 36-23

Api: 05-045-07734

Inspection # 689701269



Spool of tubing on location.

S.PARACHUTE TBI 36-23

Api: 05-045-07734

Inspection # 689701269



Trash and debri.

S.PARACHUTE TBI 36-23
Api: 05-045-07734
Inspection # 689701269



Nearest road not posted.



Nearest road not posted.

S.PARACHUTE TBI 36-23

Api: 05-045-07734

Inspection # 689701269



Weather damaged label.