



Inspection Photos

Location Name: Natural Resources Group Shannon-Roberts 1-A

Location 321499



Location sign and wellhead



Tank battery and Trash on east and west end of berms




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Natural Resources Group Shannon-Roberts 1-A

Location 321499



Leak and stained soil in dog house of separator



Separator and wellhead




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Natural Resources Group Shannon-Roberts 1-A

Location 321499



Weeds in and on tank berm area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources