

**Inspection Photo
GGU Federal 11B-33-691
API# 045-18893
Inspection # 689300882**



Location photo #1



Location Photo # 2

**Inspection Photo
GGU Federal 11B-33-691
API# 045-18893
Inspection # 689300882**



Location photo # 3



Location Photo # 4

**Inspection Photo
GGU Federal 11B-33-691
API# 045-18893
Inspection # 689300882**



Photo # 5, unused equipment



Photo # 6, unused equipment

**Inspection Photo
GGU Federal 11B-33-691
API# 045-18893
Inspection # 689300882**



Location photo # 7

Photo # 8 unprotected container, netting missing.

**Inspection Photo
GGU Federal 11B-33-691
API# 045-18893
Inspection # 689300882**



Photo #9 Tank missing information



Photo # 10 Tank missing information

**Inspection Photo
GGU Federal 11B-33-691
API# 045-18893
Inspection # 689300882**



**Photo # 11, Tank missing information.
Unprotected container, netting missing**



Photo # 12, E&P waste stored on location

**Inspection Photo
GGU Federal 11B-33-691
API# 045-18893
Inspection # 689300882**



Location photo # 13, E&P waste stored on location



Location Photo # 14, E&P waste stored on location

**Inspection Photo
GGU Federal 11B-33-691
API# 045-18893
Inspection # 689300882**



Location photo # 15, E&P waste stored on location