



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Clay Elkins (celkins@gobrainstorm.net)
Submission Date: Mar 22, 2018 10:59:52 AM MDT
Server Receive Date: Mar 22, 2018 11:00:01 AM MDT
Reference Number: 20180322-1875141862
Location: Road 4450, Blanco, NM 87412, United States
Mar 22, 2018 10:58:59 AM MDT [[View Map](#)]

Information

Name: celkins@gobrainstorm.net
Date: Mar 21, 2018
Well Name: BEEBE, GARY GAS UNIT B 2
Select State: Colorado
Work type: COGCC Inspection AR
Action Complete: Compliance Inspection Actions
Erosion Repairs
Install Rock Run Down

Picture North to South



Picture South to North



Picture East to West

