

Inspection Photo
Valley Farms L-41B-14-06-92
API# 045-22363
Inspection # 689300900



Location photo #1



Location Photo #2 Stained soil by Separators

Inspection Photo
Valley Farms L-41B-14-06-92
API# 045-22363
Inspection # 689300900



Location photo # 3 Stained soil by separators

