

**Inspection Photo  
Valley Farms F Pad  
API# 045-14285  
Inspection # 689300908**



**Location photo #1**



**Location Photo # 2**

**Inspection Photo  
Valley Farms F Pad  
API# 045-14285  
Inspection # 689300908**



**Location photo # 3, Stained material in  
Battery**



**Location Photo # 4, stained material in  
Battery**



**Inspection Photo  
Valley Farms F Pad  
API# 045-14285  
Inspection # 689300908**



**Location photo # 5, stained material in  
Battery**



**Location Photo # 6, Stained material in  
Battery**



**Inspection Photo  
Valley Farms F Pad  
API# 045-14285  
Inspection # 689300908**



**Location photo # 7, stained material in  
Battery**



**Location Photo # 8, stained material in  
Battery**



**Inspection Photo  
Valley Farms F Pad  
API# 045-14285  
Inspection # 689300908**



**Location photo # 9, stained material in battery**



**Location Photo # 10, stained material in Battery**

**Inspection Photo**  
**Valley Farms F Pad**  
**API# 045-14285**  
**Inspection # 689300908**



**Location photo # 11, stained material in Battery**



**Location Photo # 12, House keeping, stained ground**



**Inspection Photo  
Valley Farms F Pad  
API# 045-14285  
Inspection # 689300908**



**Location photo # 13, stained material in Battery**



**Location Photo # 14, leaking valve near heater unit in tank**



**Inspection Photo  
Valley Farms F Pad  
API# 045-14285  
Inspection # 689300908**



**Location photo # 15, Slope erosion behind separators**



**Location Photo # 16 slope erosion behind separators.**