



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Apr 10, 2018 7:53:56 AM MDT
Server Receive Date:	Apr 10, 2018 8:01:16 AM MDT
Reference Number:	20180410-1876420281
Location:	9 Rd 3227, Aztec, NM 87410, USA Apr 10, 2018 7:53:40 AM MDT [ <a href="#">View Map</a> ]

## Information

Name	celkins@gobrainstorm.net
Date	Apr 5, 2018
Well Name	MCMANUS GAS UNIT 33-22 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other Clean up Operator Debris Clean Up Land Owner Debris Clean Up Weed Debris Clean Up Contaminated Soils

## Picture North to South



## Picture South to North



Picture East to West



Picture West to East



Additional photos

