

Inspection Photos  
Location Name: Nielson #5  
API: 05-007-06141



Nielson #5 pump jack.



Nielson #5 pump jack and stained well head.

**Inspection Photos**  
**Location Name: Nielson #5**  
**API: 05-007-06141**



**Nielson #5 well head is wet and stained with oil.**



**Puddle of oil around well head.**

**Inspection Photos**  
**Location Name: Nielson #5**  
**API: 05-007-06141**



**Nielson #5 tank battery.**



**Well head and surrounding soil wet with oil.**