

**Inspection Photo
Valley Farms C Pad
API# 045-12204
Inspection # 689300912**



Location photo #1



**Location Photo # 2 Stained material in
containment**

Inspection Photo
Valley Farms C Pad
API# 045-12204
Inspection # 689300912



Location photo # 3, stained material in containment



Location Photo # 4, stained material in containment

**Inspection Photo
Valley Farms C Pad
API# 045-12204
Inspection # 689300912**



Location photo # 5, Hole in containment

Location Photo # 6, Hole in containment