

Inspection Photo
Knaus 30-04C
API# 045-17582
Inspection # 689300920



Location photo # 1



Location Photo # 2, hole in containment

Inspection Photo
Knaus 30-04C
API# 045-17582
Inspection # 689300920



Location photo # 3, hole in containment



Location Photo # 4, hole containment