

Inspection Photos

04/17/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 327102

Inspection Doc. Number: 682503229

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327102



Photo 1: Photo taken from the southeast end of the former tank battery location, facing east. Previous inspections required operator to perform additional reclamation activities. Operator submitted notice to inspector via email stating work has been conducted.



Photo 2: Photo taken from the southeast end of the former tank battery location, facing west.