

Inspection Photos
Well Name: Winter Flats 1-2-100
Location ID: 312565



Photo 1. Wellhead.



Photo 2. Fence damaged around separator.

Inspection Photos
Well Name: Winter Flats 1-2-100
Location ID: 312565



Photo 3. Fence damaged around tanks.



Photo 4. Erosion of cut slope and sediment run on to location.