

Inspection Photos  
Location Name: WANEKA #1-1  
Facility ID # 206633



Photo 1. Wellhead



Photo 2. Tank battery

Inspection Photos  
Location Name: WANEKA #1-1  
Facility ID # 206633



Photo 3. Unmarked risers



Photo 4. Unmarked risers