

On April 18, 2018, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of SandRidge Exploration & Production LLC's (SandRidge) Peterson Ridge 1-20H Location (Location ID: 426365) API 057-06515. Weather was sunny and temperatures about 25 degrees Fahrenheit.

The following is a summary:

- Oil staining on the ground beneath the catchment containment at the load out area.
- Salt staining (app 5' dia) on the ground beneath the catchment containment at the load out area.  
NOTE: fluids in the catchment containment were approximately ½ inch from top of lip.
- Trash and debris on location (oily rags within tank battery berm, 5-gallon pail of oil, and aerosol can).

**Corrective Actions (CAs):**

- **By April 30, 2018**, remove trash/debris. Comply with Rule 603.f using the Rule 603.f guidance document for further details.
- **By May 20, 2018**, remediate the oily stains and salty stains beneath catchment containments, valves, fittings, and unions at well head and pump jack.

*906.a, Spills/Releases, Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff., Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.*

Train and educate staff and contract personnel on house keeping with zero spills within the load out areas, and that staining beneath valves, fittings, unions, etc. may be a result of leaking/loose/weeping valves, fitting, unions, etc. that should immediately be addressed.