

**Inspection Photo  
North Bank B pad  
API# 045-10909  
Inspection # 689300928**



**Location photo # 1**



**Location Photo # 2 Tank Maintenance**

**Inspection Photo  
North Bank B pad  
API# 045-10909  
Inspection # 689300928**



**Location photo # 3 Tank Maintenance**



**Location Photo # 4 Holes in Containment**

**Inspection Photo  
North Bank B pad  
API# 045-10909  
Inspection # 689300928**




**Location photo # 5 Holes in Containment**



**Location Photo # 6 holes in Containment**

**Inspection Photo  
North Bank B pad  
API# 045-10909  
Inspection # 689300928**



**Location photo # 7, condensate in drip pan**



**Location Photo # 8 Stained ground**