

# *Inspection Photos*

*API#077-08721*

*Operator: Laramie Energy*

*Inspection Number: 680102889*

*Inspection Date: 4/16/2018*





**Photo#1:**

There is what appears to be unused equipment on site, that maybe associated with the PA Well.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie PA BC API#077-08721



**Photo#2:**

There is what appears to be unused equipment on site, that maybe associated with the PA Well.

April 16, 2018