

Inspection Photos

Loc#312666

Operator: Laramie Energy

Inspection Number: 680102893

Inspection Date: 4/16/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from top of Cut slope to West.

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#312666



Photo#2:

View of ditch & check dams that run along fill slope.

*

April 16, 2018



Photo#3:

The last check dam to West on upper fill slope ditch has cutout where Stormwater is bypassing BMP.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#312666



Photo#4:

Stock trail at top of Cut slope maybe leading to commencement of rill erosion on one section of Cut slope indicated with red in Photo#5. Stormwater is bypassing rocked drain.

April 16, 2018



Photo#5:



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Loc#312666



Photo#6:

Maintenance is needed on check dams & rocked drains.

April 16, 2018



Photo#7: