

# *Inspection Photos*

*Loc#334554*

*Operator: Laramie Energy*

*Inspection Number: 680102900*

*Inspection Date: 4/16/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Photo#1:**  
Overview of Location from entry to North.

April 16, 2018



Photo#2:  
Debris is scattered over Location.

April 16, 2018



Photo#3:



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie BCU Loc #334554





Photo#4:  
Debris is scattered over Location.

April 16, 2018



Photo#5:  
Unused equipment on Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie BCU Loc #334554



Photo#6:  
Unused equipment, supplies stored on Location.



Photo#7:

April 16, 2018





Photo#8:  
Unmarked Anchor.

April 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie BCU Loc #334554