

Inspection Photos  
Location Name: Govt-Winder 1  
API: 05-081-05370



**Photo 1. Overview of location taken at entrance facing southwest.**



**Photo 2. Unmarked 1" steel riser, cellar full of water.**