

Inspection Photos

Loc#3344486

Operator: Laramie Energy

Inspection Number: 680102903

Inspection Date: 4/16/2018





Photo#1:
Overview of Location from Entry to North.

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: LaramieLoc#3344486



Photo#2:

Areas of Location no longer needed for Use have not been Reclaimed.

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: LaramieLoc#3344486




Photo#3:
Site 2010 Aerial.

April 16, 2018



Photo #4 :
Site 2016 Aerial



Photo#5: Sediment traps & drains leading to & at base of Fill slope have failed.

Photo#6:

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: LaramieLoc#3344486



Photo#4:
Installed drain from top of fill slope has been damaged by livestock.

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#5:
Sediment is migrating off site at base of fill slope.

Inspection Photos: LaramieLoc#3344486



Photo#6:

Wattles have been damaged, reached end of functional life & become debris.



Photo#7:

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: LaramieLoc#3344486



Photo#7:
Installation at Southwest area of site appears to be unused.

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: LaramieLoc#3344486



Photo#8:
Anchors need to be marked or removed.



Photo#9:

April 16, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: LaramieLoc#3344486