

Inspection Photos
Location Name: Owl Creek 8-64-30 #1H
Location: 423948



Photo 1: Wellhead, looking NW



Photo 2: Location, looking NE

Inspection Photos
Location Name: Owl Creek 8-64-30 #1H
Location: 423948



Photo from prior inspection for comparison

Photo 3: Wellhead sign corrected

Inspection Photos
Location Name: Owl Creek 8-64-30 #1H
Location: 423948



Photo from prior inspection for comparison

Photo 4: Lease sign corrected.

Inspection Photos
Location Name: Owl Creek 8-64-30 #1H
Location: 423948



Photo 5: Unused pipe, equipment at pump jack.



Photo 6: Weeds in tank battery



Inspection Photos
Location Name: Owl Creek 8-64-30 #1H
Location: 423948



Photo 7: Debris on S side of location.

