

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/26/2018

Submitted Date:

04/26/2018

Document Number:

689300968**FIELD INSPECTION FORM**

Loc ID 323991	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 21 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																																							
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>																																																																																																											
Contact Information: <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Rocky, TEP</td> <td></td> <td>COGCCInspectionReports@terraep.com</td> <td>All Inspections</td> </tr> </table>					Contact Name	Phone	Email	Comment	Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections																																																																																															
Contact Name	Phone	Email	Comment																																																																																																								
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections																																																																																																								
Inspected Facilities: <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>211434</td><td>WELL</td><td>PR</td><td>08/01/2014</td><td>GW</td><td>045-07194</td><td>BERNKLAU RMV 108-4</td><td>PR</td></tr> <tr><td>433486</td><td>WELL</td><td>PR</td><td>03/03/2014</td><td>GW</td><td>045-22081</td><td>WPX Energy RWF 332-4</td><td>PR</td></tr> <tr><td>433487</td><td>WELL</td><td>PR</td><td>07/17/2014</td><td>GW</td><td>045-22082</td><td>WPX Energy RWF 341-4</td><td>PR</td></tr> <tr><td>433488</td><td>WELL</td><td>PR</td><td>04/01/2014</td><td>GW</td><td>045-22083</td><td>WPX Energy RWF 442-4</td><td>PR</td></tr> <tr><td>433489</td><td>WELL</td><td>PR</td><td>03/01/2014</td><td>GW</td><td>045-22084</td><td>WPX Energy RWF 342-4</td><td>PR</td></tr> <tr><td>433490</td><td>WELL</td><td>PR</td><td>02/28/2014</td><td>GW</td><td>045-22085</td><td>WPX Energy RWF 422-4</td><td>PR</td></tr> <tr><td>433491</td><td>WELL</td><td>PR</td><td>01/15/2014</td><td>OW</td><td>045-22086</td><td>WPX Energy RMV 163-4</td><td>PR</td></tr> <tr><td>433492</td><td>WELL</td><td>PR</td><td>02/28/2014</td><td>GW</td><td>045-22087</td><td>WPX Energy RWF 421-4</td><td>PR</td></tr> <tr><td>433493</td><td>WELL</td><td>PR</td><td>08/01/2014</td><td>GW</td><td>045-22088</td><td>WPX Energy RWF 42-4</td><td>PR</td></tr> <tr><td>433494</td><td>WELL</td><td>PR</td><td>08/01/2014</td><td>GW</td><td>045-22089</td><td>WPX Energy RWF 32-4</td><td>PR</td></tr> <tr><td>433495</td><td>WELL</td><td>PR</td><td>02/14/2014</td><td>GW</td><td>045-22090</td><td>WPX Energy RWF 331-4</td><td>PR</td></tr> <tr><td>433496</td><td>WELL</td><td>PR</td><td>02/28/2014</td><td>GW</td><td>045-22091</td><td>WPX Energy RWF 523-4</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	211434	WELL	PR	08/01/2014	GW	045-07194	BERNKLAU RMV 108-4	PR	433486	WELL	PR	03/03/2014	GW	045-22081	WPX Energy RWF 332-4	PR	433487	WELL	PR	07/17/2014	GW	045-22082	WPX Energy RWF 341-4	PR	433488	WELL	PR	04/01/2014	GW	045-22083	WPX Energy RWF 442-4	PR	433489	WELL	PR	03/01/2014	GW	045-22084	WPX Energy RWF 342-4	PR	433490	WELL	PR	02/28/2014	GW	045-22085	WPX Energy RWF 422-4	PR	433491	WELL	PR	01/15/2014	OW	045-22086	WPX Energy RMV 163-4	PR	433492	WELL	PR	02/28/2014	GW	045-22087	WPX Energy RWF 421-4	PR	433493	WELL	PR	08/01/2014	GW	045-22088	WPX Energy RWF 42-4	PR	433494	WELL	PR	08/01/2014	GW	045-22089	WPX Energy RWF 32-4	PR	433495	WELL	PR	02/14/2014	GW	045-22090	WPX Energy RWF 331-4	PR	433496	WELL	PR	02/28/2014	GW	045-22091	WPX Energy RWF 523-4	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																				
211434	WELL	PR	08/01/2014	GW	045-07194	BERNKLAU RMV 108-4	PR																																																																																																				
433486	WELL	PR	03/03/2014	GW	045-22081	WPX Energy RWF 332-4	PR																																																																																																				
433487	WELL	PR	07/17/2014	GW	045-22082	WPX Energy RWF 341-4	PR																																																																																																				
433488	WELL	PR	04/01/2014	GW	045-22083	WPX Energy RWF 442-4	PR																																																																																																				
433489	WELL	PR	03/01/2014	GW	045-22084	WPX Energy RWF 342-4	PR																																																																																																				
433490	WELL	PR	02/28/2014	GW	045-22085	WPX Energy RWF 422-4	PR																																																																																																				
433491	WELL	PR	01/15/2014	OW	045-22086	WPX Energy RMV 163-4	PR																																																																																																				
433492	WELL	PR	02/28/2014	GW	045-22087	WPX Energy RWF 421-4	PR																																																																																																				
433493	WELL	PR	08/01/2014	GW	045-22088	WPX Energy RWF 42-4	PR																																																																																																				
433494	WELL	PR	08/01/2014	GW	045-22089	WPX Energy RWF 32-4	PR																																																																																																				
433495	WELL	PR	02/14/2014	GW	045-22090	WPX Energy RWF 331-4	PR																																																																																																				
433496	WELL	PR	02/28/2014	GW	045-22091	WPX Energy RWF 523-4	PR																																																																																																				

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211434	WELL	PR	08/01/2014	GW	045-07194	BERNKLAU RMV 108-4	PR
433486	WELL	PR	03/03/2014	GW	045-22081	WPX Energy RWF 332-4	PR
433487	WELL	PR	07/17/2014	GW	045-22082	WPX Energy RWF 341-4	PR
433488	WELL	PR	04/01/2014	GW	045-22083	WPX Energy RWF 442-4	PR
433489	WELL	PR	03/01/2014	GW	045-22084	WPX Energy RWF 342-4	PR
433490	WELL	PR	02/28/2014	GW	045-22085	WPX Energy RWF 422-4	PR
433491	WELL	PR	01/15/2014	OW	045-22086	WPX Energy RMV 163-4	PR
433492	WELL	PR	02/28/2014	GW	045-22087	WPX Energy RWF 421-4	PR
433493	WELL	PR	08/01/2014	GW	045-22088	WPX Energy RWF 42-4	PR
433494	WELL	PR	08/01/2014	GW	045-22089	WPX Energy RWF 32-4	PR
433495	WELL	PR	02/14/2014	GW	045-22090	WPX Energy RWF 331-4	PR
433496	WELL	PR	02/28/2014	GW	045-22091	WPX Energy RWF 523-4	PR

General Comment: Routine Field Inspection

Location				
Lease Road:				
Type	Main			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:	1-970-285-9377			
Corrective Action:				Date:
Good Housekeeping:				
Type	WEEDS			
Comment:	Dead Weeds around location			
Corrective Action:	Comply with Rule 603.f .			Date: 05/07/2018
Type	TRASH			
Comment:	Overall good			
Corrective Action:				Date:
Type	DEBRIS			
Comment:	Overall good			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	SEPARATOR			
Comment:	Hog Panel fencing			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Livestock gates			
Corrective Action:				Date:
Equipment:				
Type: Deadman # & Marked	# 4			corrective date
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 3			
Comment:	Chemical units at Wellheads			
Corrective Action:				Date:

Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	211434	Type:	WELL	API Number:	045-07194	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	433486	Type:	WELL	API Number:	045-22081	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	433487	Type:	WELL	API Number:	045-22082	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	433488	Type:	WELL	API Number:	045-22083	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	433489	Type:	WELL	API Number:	045-22084	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	433490	Type:	WELL	API Number:	045-22085	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	433491	Type:	WELL	API Number:	045-22086	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	433492	Type:	WELL	API Number:	045-22087	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID: 433493 Type: WELL API Number: 045-22088 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID: 433494 Type: WELL API Number: 045-22089 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID: 433495 Type: WELL API Number: 045-22090 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID: 433496 Type: WELL API Number: 045-22091 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
		Compaction				
				Material Handling And Spill Prevention		
Seeding						
Slope Roughening						
Hydro Mulch						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300969	DocNum: 689300968.4/26/18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4446185