

File w/state report

Donnelly Casing Pulling Co.

Phone 522-1410

P.O. Box 791
Sterling, Colorado 80751**RECEIVED**

JAN 8 1976

SOLD TO Mr. Larry Hartnett
Charter Oil Company
Roggen, Colorado 80652

00026861

INVOICE DATE 12-10-75
CONS. COMM.

WELL Baumgardner 1-A

INVOICE NO. 146

Pulled rods & tubing

5860' 4 1/2" OD Casing @

Day Work, 41 hours @

Water Truck, 27 hours @

Cement, 42 sacks @

Water, 4 loads @

Pump, 1 job @

50¢ per foot

\$20.00 per hour

\$15.00 per hour

\$3.25 each + tax

\$5.00 per load

\$200.00 per job

\$ 500.00

2930.00

820.00

405.00

140.60

20.00

200.00

\$5015.60*Larry Hartnett*
REMARKS

DATE	DAY WORK	REMARKS
11-24-75	3 hours	Moved unit. Dug deadmen. Bled well in water truck. Water truck, 3 hours.
11-25-75	0 hours	Drove to work. Road closed.
11-28-75	3 hours	Waited for well to bleed down. Pulled 210 rods.
11-29-75	0 hours	Pulled 87 rods, 123 tubing.
12- 1-75	0 hours	Pulled 103 tubing. Waited for plugs to be set. Dug cellar. <u>Set 2 sacks cement on plug.</u>
12- 2-75	0 hours	Set in floor. Worked pipe to 62". Loaded the hole. Ran shot to 5945'. Worked pipe to 65".
12- 3-75	0 hours	Worked pipe. Ran shot to 5830'. Worked pipe.
12- 4-75	0 hours	Worked pipe to 65". No pump truck.
12- 5-75	9 hours	Pumped 5 bbls. water. Worked pipe. Pumped 40 bbls. oil. No pit. Couldn't get cat to wig pit. Water truck, 9 hours.
12- 6-75	5 hours	Pumped 90 bbls. water. Worked pipe to 19". Water truck, 5 hours. Pump job. 2 loads water.
12- 8-75	0 hours	Worked pipe to 65".
12- 9-75	0 hours	Worked pipe to 71".
12-10-75	8 hours	Worked pipe. Checked in. Plug at 5200'. Pumped 50 bbls. water. Water truck, 4 hours. 1 load water.
12-11-75	0 hours	Worked pipe to 19".

File