

Inspection Photos

Loc#334501

Operator: Laramie Energy

Inspection Number: 680102912

Inspection Date: 4/18/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

View Over Location to Northwest. Areas no longer needed for use have not been reclaimed

April 18 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gipp Loc#334501



Photo#2:

View Over Location to North. Areas no longer needed for use have not been reclaimed.

April 18 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gipp Loc#334501



Photo#3: Site 2010 Aerial.

Aerial views of Location, showing that Pad size has not been Reduced sine 2010 Completion of Wells.

Photo#4: Site 2016 Aerial.

April 18 2018