

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/30/2018

Submitted Date:

04/30/2018

Document Number:

679904331

FIELD INSPECTION FORM

Loc ID 311247 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10489
Name of Operator: AUGUSTUS ENERGY RESOURCES LLC
Address: 2016 GRAND AVENUE #A
City: BILLINGS State: MT Zip: 59102

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 332-3585	gjones@augustusenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300431	WELL	PR	05/01/2010	GW	125-11641	PARISET 20-12	PR

General Comment:

Routine Inspection

Location

Lease Road:			
	Type	Access	
	comment:	Trail through farm ground	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:	Lease sign by wellhead	
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:		
	Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
	Type	PUMP JACK	
	Comment:	Metal panels around unit and wellhead	
Corrective Action:			Date:

Equipment:			corrective date
Type:	Ancillary equipment	# 1	
	Comment:	Gas scrubber	
Corrective Action:			Date:
Type:	Pump Jack	# 1	
	Comment:	Jensen unit	
Corrective Action:			Date:
Type:	Prime Mover	# 1	
	Comment:	Kubota gas engine	
Corrective Action:			Date:

Venting:			
	Yes/No	NO	
	Comment:		
Corrective Action:			Date:

Flaring:			
Type			

Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 300431 Type: WELL API Number: 125-11641 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Stults 20-6 and 20-3, Pariset 20-12\) 870' NW of wellhead](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

Comment: [Access is farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT