

**Inspection Photo**  
**Dunn 4-13C**  
**API# 045-13385**  
**Inspection # 689301010**




**Location photo # 1**



**Location photo #2**



**Inspection Photo**  
**Dunn 4-13C**  
**API# 045-13385**  
**Inspection # 689301010**



**Location photo # 3**



**Location photo #4 Holes in tank battery containment**



**Inspection Photo**  
**Dunn 4-13C**  
**API# 045-13385**  
**Inspection # 689301010**



**Location photo # 5, Holes in tank battery  
containment**



**Location photo #6, Holes in tank battery  
containment**

**Inspection Photo**  
**Dunn 4-13C**  
**API# 045-13385**  
**Inspection # 689301010**



**Location photo # 7, Holes in tank battery containment**



**Location photo #8, Holes in tank battery containment**



**Inspection Photo**  
**Dunn 4-13C**  
**API# 045-13385**  
**Inspection # 689301010**



**Location photo # 9, Holes in tank battery  
containment**

**Location photo #2**

