

Inspection Photos
Location Name: JB Gardner A #1
API: 05-067-07587



PBV and skid mounted compressor.



Proximity of Spill/Release Point ID #454831 to JB Gardner A #1 production equipment.

Inspection Photos
Location Name: JB Gardner A #1
API: 05-067-07587



Excavation of 4" steel produced water line.



Locked out valve at Hendrickson Water Injection Facility.

Inspection Photos
Location Name: JB Gardner A #1
API: 05-067-07587



Excavation behind production equipment for JB Gardner A #1.



Track hoe excavating 4" water transfer line.

Inspection Photos
Location Name: JB Gardner A #1
API: 05-067-07587



Access road where release terminated.



Photo taken from reported termination of release.