

Inspection Photos
Location Name: NWCH 32-10 #12
API: 05-067-05035



Location sign and fiberglass open topped tank.



Fiberglass open topped 20 bbl. tank.

Inspection Photos
Location Name: NWCH 32-10 #12
API: 05-067-05035



Gravel berm has sloughed off into containment area. Liner is torn.



NWCH 32-10 #12 well head.