

Inspection Photo
Twin Creek 12-5A (F12E)
API# 045-20385
Inspection # 689301012



Location photo # 1



Location photo #2

Inspection Photo
Twin Creek 12-5A (F12E)
API# 045-20385
Inspection # 689301012



Location photo # 3, Stained ground North end of tank battery

Location photo #4, Stained ground North end of tank battery

Inspection Photo
Twin Creek 12-5A (F12E)
API# 045-20385
Inspection # 689301012



Location photo #5, Stained ground at wellhead



Location photo #6, Condensate in tank battery containment

Inspection Photo
Twin Creek 12-5A (F12E)
API# 045-20385
Inspection # 689301012



**Location photo #7, Condensate in tank
battery**