

**Inspection Photo
Twin Creek 1-15B (O1E)
API# 045-09215
Inspection # 689301016**



Location photo # 1



**Location photo #2, Stained ground near
separators**

Inspection Photo
Twin Creek 1-15B (O1E)
API# 045-09215
Inspection # 689301016



Location photo #3, Stained ground near separators



Location photo #4, Stained ground near separators