

Inspection Photos

Loc#422211

Operator: Terra

Inspection Number: 680102925

Inspection Date: 4/28/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southeast.

April 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Loc#422211



Photo#2:
Sediment trap at base of fill slope. View to South

April 28, 2018



Photo #3:
Sediment trap at base of fill slope. View to North



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Loc#422211



Photo#4:
Soil stockpile at South end of Location; view to West.

April 28, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Loc#422211



Photo#5:
Views along toe of fill

April 28, 2018



Photo#6:



Photo#7:
Soil stockpile at South end of Location; view to East.

April 28, 2018



Photo#8:
View along cut slope to North