

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2018

Submitted Date:

04/26/2018

Document Number:

684905342**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 306734      Pesicka, Conor      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON      State: TX      Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290625	WELL	SI	09/01/2016	OW	123-25171	DILLARD 4-24	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	propane		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment around pump jack, separator		
Corrective Action:	Comply with rule 603.f.	Date:	07/26/2018

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:				Date:	
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	gas engine				
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	containers- 1 propane				
Corrective Action:				Date:	
Type: Pig Station	# 1				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS		40.601560,-104.554020
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	75bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with crude oil			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		40.601560,-104.554020	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	PBV CONCRETE		40.601560,-104.554020	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)		48bbl				
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:		Shared with crude oil				
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities										
Facility ID:	290625	Type:	WELL	API Number:	123-25171	Status:	SI	Insp. Status:	TA	
Idle Well										
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED				
Comment:		<a href="#">TA. Variance on MIT requirement per doc#401474555.</a>								
Corrective Action:								Date:		
BradenHead										
Comment:		<a href="#">Bradenhead plumbed to surface.</a>								
Corrective Action:								Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401621426	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4446074">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4446074</a>
684905343	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4446072">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4446072</a>