

Interim Reclamation Inspection

April 27, 2018

Operator: HIGHPOINT OPERATING CORPORATION- 10071

Location ID: 449306

Inspection Document #: 682403531

Weld County, CO

NWSW Section 32 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CVR /5-63-32_33 NWSW
Location ID: 449306



Photo 1. Photo taken from the southern well pad area, facing Northwest. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations. A follow-up interim reclamation inspection will be conducted at a future date to ensure compliance with Rule 1003.

Inspection Photos

Location Name: CVR /5-63-32_33 NWSW

Location ID: 449306




Photo 2. Photo taken from the southern well pad area, facing Northeast. See comments under Photo 1.

Inspection Photos

Location Name: CVR /5-63-32_33 NWSW

Location ID: 449306



Photo 3. Photo taken from the southern well pad area, facing East. See comments under Photo 1.

Inspection Photos

Location Name: CVR /5-63-32_33 NWSW

Location ID: 449306



Photo 4. Photo taken from the southern well pad area, facing West. See comments under Photo 1.