

**Forshee GV 86-2**  
**Api: 05-045-06703**  
**Inspection # 689701317**



**Forshee GV 86-2 Pad**  
**Location photo**

**Forshee GV 86-2**  
**Api: 05-045-06703**  
**Inspection # 689701317**



**Forshee GV 86-2**



**Forshee W-28-2**

**Forshee GV 86-2**  
**Api: 05-045-06703**  
**Inspection # 689701317**



**Weed debris around wells.**



**Forshee GV 86-2**  
**Api: 05-045-06703**  
**Inspection # 689701317**



**Weed debris around wells.**

Forshee GV 86-2  
Api: 05-045-06703  
Inspection # 689701317



Weed debris around separators.



**Forshee GV 86-2**  
**Api: 05-045-06703**  
**Inspection # 689701317**



**Weed debris around separators.**

**Forshee GV 86-2**  
**Api: 05-045-06703**  
**Inspection # 689701317**



**Weed debris around separators.**

**Forshee GV 86-2**  
**Api: 05-045-06703**  
**Inspection # 689701317**



**Volumes are faint on labels.**



**Volumes are faint on labels.**