

Inspection Photos
Location Name: Federal 6-2
Location ID: 312460




Photo 1. Snapshot from location FLIR video. To leaks or venting observed at the time of the inspection.




Photo 2. Snapshot from riser FLIR video. To leaks or venting observed at the time of the inspection.