23-2N-58W

PHO. LA 2-1206 **VIRG'S TESTERS, INC.** BOX 712—STERLING, COLO.



Company Operating Well
Tipps Drlg. Co., Inc.

Address
914 Patterson Bldg.
Denver 2, Colorado

Contractor and Rig No.
Tipps Drlg. Co. Rig # 2

Well Name and No.
B. M. Young # 1

County	State
Morgan	Colorado

Sec.	Twn.	Rng.
23	2 N	58 W

Ticket	DST No.	Tester
6564	1	Byrd

Date of Test and Formation Tested
4-2-63 "D" Sand

		Field Pressure	Corrected Pressure
Initial Hydrostatic:	A	2995	2998
Final Hydrostatic:	F	2955	2981
Initial Flow:	C	61	62
Final Flow:	D	114	121
Initial Shut-in:	B	420	427
Final Shut-in:	E	405	417
Press. below bottom packer bled to:		1200	1200

RESULTS

Total Depth 5646 Interval tested 5630-5636
Tool open for 60 mins. Initial Shut-in 20 mins Final Shut-in 20 min
Tool open @ 12:15 p. M Mud Wt. 9.9 Vis. 105
Did well flow Gas? No
Did well flow Oil? No
Did well flow Water? No Witnessed by:
Was Blow measured? No
EXTRA EQUIPMENT: Jars? Yes Safety Jt.? Yes R. Sub?
Extra packers? No No. final copies? 5
Cost of Test? $485 Top Choke 1" Bottom Choke 9/16" D. P. Size 4½" X. H
Recorder No. 1389 Run At 5615 Was this a straddle test? Yes
Recovery in D. P. 290' of sl/ oil cut water.
1260' of gas in drill pipe.

REMARKS: Tool open with a fair blow increased to good blow in 15 minutes. Decreased to fair blow at the end of 45 minutes & remained fair throughout test.

Test Conclusive.

RECEIVED
APR 17 1963
OIL & GAS
CONSERVATION COMMISSION

00105331