

Inspection Photos

05/04/2018

Operator: WIEPKING-FULLERTON ENERGY LLC -
96340

Location ID: 438714

Inspection Doc. Number: 682503303
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 438714



Photo 1: Photo taken from the east end of the location, facing southwest. Photo shows the vegetation over the reclamation area. Reclamation in process.



Photo 2: Photo taken from the east end of the location, facing west. Photo shows the vegetation over the reclamation area. Reclamation in process.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 438714



Photo 3: Photo taken from the east end of the location, facing northwest. Photo shows the vegetation over the reclamation area. Reclamation in process.



Photo 4: Photo taken from the southern area of the location, facing west. Photo shows areas of the reclamation area where reclamation does not appear to be progressing as well as other areas of the location; additional revegetation activities may be required.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 438714



Photo 5: Photo taken from the southern area of the location, facing east. Photo shows areas of the reclamation area where reclamation does not appear to be progressing as well as other areas of the location; additional revegetation activities may be required.



Photo 6: Photo taken from the south end of the location, facing south. Photo shows the vegetation over the reclamation area. Reclamation in process.



Photo 7: Photo taken from the access road, facing east. Photo shows sections of access road where vegetation does not appear to be establishing. Additional revegetation activities may be required.