

Inspection Photo
Clough RWF 333-14
API# 045-11202
Inspection # 689301051




Location photo # 1



Location photo #2,

Inspection Photo
Clough RWF 333-14
API# 045-11202
Inspection # 689301051



Location photo # 3 Tank label peeling off



Location photo #4, Slope erosion East end of location

Inspection Photo
Clough RWF 333-14
API# 045-11202
Inspection # 689301051



Location photo # 5, Slope erosion East end of location



Location photo # 6, Slope erosion East end of location

**Inspection Photo
Clough RWF 333-14
API# 045-11202
Inspection # 689301051**



Location photo # 7, Slope erosion East end of location



Location photo #8, Slope erosion East end of location