

# *Inspection Photos*

*Loc#436196*

*Operator: Ursa*

*Inspection Number: 680102931*

*Inspection Date: 4/30/2018*





Photo#1:  
Overview of Location from entry to South.

April 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa Loc#436196



Photo#2:  
Overview of Location to East.

April 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa Loc#436196



Photo#3:  
Tanks stored adjacent to Location access road.

April 30, 2018



Photo#4:  
Close up of Contents of Poly Totes.



Photo#5:

April 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa Loc#436196



Photo#6:  
The same material in Poly Totes was also noted on ground by tanks.



Photo#7:

April 30, 2018



Photo#8:  
Totes have tears & are not closed.

April 30, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Ursa Loc#436196